



REPORT TO THE CITY OF PEORIA COMMUNITY SERVICES DEPARTMENT

Section 2: Peoria Community Center

July 1, 2013

Legend of Abbreviations

aff... above the finished floor (or
above the finished ground)
AR... Accessible Route
CIL... Change in Level
CFS... Clear Floor Space
lbf... Pounds of Force

Background

RAC staff conducted an access audit at the Peoria Community Center. Our findings are below.

- 1.1 Parking - [CHECKLIST]** first front access aisle too narrow for van stall (checklist); first stall in at historic buildings 2.4% slope [CC3](#), [CC4](#); sign heights low- 2 front stalls at 56" [CC1](#), [CC2](#), 2 front stalls at 59" (checklist), 2 side stalls at 56" (checklist)

Recommendations (Peoria Community Center is a site designated with accessible features so 1.1.1 through 1.1.3 is integral to compliance with title II program access test):

- 1.1.1 **Repaint** van stall and access aisle to 11' and 5' or 8' and 8' (checklist)
- 1.1.2 **Repair or correct slope** of parking space and access aisle to max 2.08% in any direction (CC3, CC4)
- 1.1.3 **Raise** existing accessible parking signs so lowest end of bottom sign is min 60" aff (CC1, CC2, checklist)

Responsible Employee	Progress Towards Completion	Recommended Phase
Brenda Rehnke Recreation Manager 623-773-7131	(insert periodic notes regarding steps taken or work completed)	PHASE ONE

- 1.2 Exterior Accessible Route (includes common area and stairs)- [CHECKLIST]**

3 tables lack toe clearance due to table legs [CC9](#); lacks curb cut at passenger loading area on street [CC7](#); AR width reduces due to chair [CC8](#); .5" CIL to benches [CC5](#), [CC6](#); passenger loading aisles not marked [CC7](#)

Recommendations (Peoria Community Center is a site designated with accessible features so 1.2.1 through 1.2.5 is integral to compliance with title II program access test):

- 1.2.1 **Replace one picnic table** with one with knee and toe clearance, 9" deep at 27" high and 25" deep at 9" high, with a 36" AR around table on exterior of building (CC9)
- 1.2.2 **Create a** curb ramp to be max running slope 8.33%, max cross slope 2.08%, having a top landing as wide as the ramp and 36" deep and side flares with a max slope 10% connecting street side passenger loading zone to AR (CC7)
- 1.2.3 **Relocate** chair to not interfere with AR (CC8)
- 1.2.4 **Repair, bevel, or ramp** CIL along AR (CC5, CC6)
- 1.2.5 **Designate** an access aisle for the passenger drop off area by painting an aisle that is 60" wide and 20' long (CC7)

Responsible Employee	Progress Towards Completion	Recommended Phase
Brenda Rehnke Recreation Manager 623-773-7131	(insert periodic notes regarding steps taken or work completed)	PHASE ONE

1.3 Exterior Entry Signage - [\[CHECKLIST\]](#) accessible entries lack symbol (checklist)

Recommendations (Peoria Community Center is a site designated with accessible features so 1.3.1 is integral to compliance with title II program access test):

1.3.1 **Mount signage** at entrances designating as accessible (checklist)

Responsible Employee	Progress Towards Completion	Recommended Phase
Brenda Rehnke Recreation Manager 623-773-7131	(insert periodic notes regarding steps taken or work completed)	PHASE ONE

1.4 Exterior Entry Doors - [\[CHECKLIST\]](#)

Maneuvering Clearance: tot playground- 3.8% slope pull side [CC28](#), [CC29](#); tot gate-lacks 18" on pull side [CC30](#); Calderwood kitchen exit- coolers push side [CC57](#), 1.25" gap pull side [CC55](#), [CC56](#)

Gaps: main entry auto- 1" [CC11](#), [CC12](#)

Hardware: tot gate- pull side too small (checklist); entry near saddleback- auto opener fails due to door catching on manual door (checklist)

LBF: 5 of 5 exterior doors exceed 8.5 lbf (checklist)

Closer: 3 of 5 exterior doors close too fast (checklist)

Sidelight/Viewing Window: tot playground- 51" [CC26](#), [CC27](#); Calderwood kitchen exit- 47.5" (checklist)

Recommendations (Peoria Community Center is a site designated with accessible features so 1.4.1 through 1.4.11 is integral to compliance with title II program access test):

1.4.1 For all doors along the public circulation route, **correct or repair slope** at doorway landing to max 2.08% in any direction for level CFS (CC28, CC29)

1.4.2 For all doors along the public circulation route, **widen** pathway approaching entry to extend 18" beyond latch side of door for maneuvering clearance (CC30)

- 1.4.3 For all doors along the public circulation route, **relocate storage, furniture, and other obstacles** to create 60" maneuvering space around door (CC57)
- 1.4.4 For all doors along the public circulation route, **fill and maintain** gaps in maneuvering clearance at doorways to max .5" (CC55, CC56)
- 1.4.5 For all doors along the public circulation route, **fill and maintain** gaps at doorways to max .5" (CC11, CC12)
- 1.4.6 For all doors along the public circulation route, **replace hardware** with lever hardware where indicated (checklist)
- 1.4.7 For all doors along the public circulation route, **adjust** door seal to allow power door to open upon activation (checklist)
- 1.4.8 For all doors along the public circulation route, **inspect, adjust, and maintain** 8.5 lbf to open exterior doors as a smart practice (checklist)
- 1.4.9 For all doors along the public circulation route, **inspect, adjust, and maintain** closing speed on door closers so that doors do not close to 3" faster than 3 seconds when started at 70 degrees (checklist)
- 1.4.10 For all doors along the public circulation route, **replace doors** with ones having sidelight viewing windows max 43" aff (CC26, CC27, checklist)
- 1.4.11 **Upon renovation**; make above corrections to employee only doors

Responsible Employee	Progress Towards Completion	Recommended Phase
Brenda Rehnke Recreation Manager 623-773-7131	(insert periodic notes regarding steps taken or work completed)	PHASE ONE

1.5 Elevator or Lift - not applicable

1.6 Interior Doors - [\[CHECKLIST\]](#)

Maneuvering Clearance: storage near main entry- storage push side [CC10](#); family restroom- 16" to drinking fountain pull side [CC14](#), [CC15](#); east wing storage (chair and table)- storage push side [CC16](#); east/west to kitchen- 11.75" to counter push side [CC19](#), [CC20](#); kitchen to tot- fire extinguisher and cart push side [CC23](#); janitor storage- storage on push side [CC33](#); twin buttes A storage- storage push side [CC36](#); snack storage- advertising board pull side [CC37](#); Calderwood B storage- interior storage [CC45](#); kitchen storage right- equipment push side, counter pull side [CC48](#); kitchen storage left- sink pull side, ice machine prevents from opening fully [CC54](#); Calderwood janitor storage- interior storage [CC58](#); stage storage A- push side storage and ladder [CC59](#); stage storage B- pull side storage [CC60](#); stage storage C- pull side storage, curtain push side [CC61](#), [CC62](#); break room entry- recessed push side [CC63](#), [CC64](#); saddleback storage- [CC66](#)

Dimension (32"X80"): 15 doors fail- east wing storage (chair and table)- [CC17](#), [CC18](#); twin buttes A storage- [CC34](#), [CC35](#); men's restroom near twin buttes- [CC42](#), [CC43](#); women's restroom near twin buttes- [CC44](#); kitchen storage right- [CC50](#), [CC49](#); kitchen storage left- [CC53](#); east/west to kitchen, kitchen to tot, tot restroom, twin buttes B storage, stage storage B, stage storage C, break room to cubicles, Paula's office,

cubicles to meeting room (checklist); snack storage- half door shelf protrudes 6.25"
[CC40](#), [CC41](#)

Hardware: janitor storage- lacks knurled (checklist); snack storage- 33" [CC38](#), [CC39](#)

LBF: 12 of 12 interior doors exceed 5 lbf (checklist)

Closer: 2 of 12 interior doors close too fast (checklist)

Sidelights/Viewing Windows: east/west to kitchen- 47.25" [CC21](#), [CC22](#); kitchen to tot- 47.75" [CC24](#), [CC25](#); Calderwood kitchen entry- 47.25" [CC46](#), [CC47](#)

Recommendations (Peoria Community Center is a site designated with accessible features so 1.6.1 through 1.6.12 is integral to compliance with title II program access test):

- 1.6.1 For all doors along the public circulation route, **relocate storage, furniture, and other obstacles** to create 60" maneuvering space around doors (CC10, CC16, CC23, CC33, CC36, CC37, CC45, CC48, CC58, CC59, CC60, CC61, CC62, CC66)
- 1.6.2 For all doors along the public circulation route, **remove and rehang** door to open from the opposite side to create 18" of maneuvering clearance on the pull side (CC14, CC15)
- 1.6.3 **Leave as is**, maneuvering clearance at east/west to kitchen; cite construction tolerance (CC19, CC20)
- 1.6.4 For all doors along the public circulation route, **remove and rehang** to swing inward rather than outward to provide 18" maneuvering clearance on the pull side of door (CC54)
- 1.6.5 For all doors along the public circulation route, **widen entries** to allow for 12" of maneuvering clearance on the push side of doorway (CC63, CC64)
- 1.6.6 For all doors along the public circulation route, **replace doors** with doors having 80" overhead clearance and 32" clear width (CC17, CC18, CC34, CC35, CC42, CC43, CC44, CC50, CC49, CC53, CC40, CC41, checklist)
- 1.6.7 For all doors along the public circulation route, **replace hardware** on doors to hazardous areas with knurled lever hardware as a smart practice (checklist)
- 1.6.8 For all doors along the public circulation route, **remount hardware** to 34" to 48" aff (CC38, CC39)
- 1.6.9 For all doors along the public circulation route, **inspect, adjust, and maintain 5 lbf** to open interior doors (checklist)
- 1.6.10 For all doors along the public circulation route, **inspect, adjust, and maintain** closing speed on door closers so that doors do not close to 3" faster than 3 seconds when started at 70 degrees (checklist)
- 1.6.11 For all doors along the public circulation route, **replace doors** with ones having sidelight viewing windows max 43" aff (CC21, CC22, CC24, CC25, CC46, CC47)
- 1.6.12 For employee only doors; make above corrections **upon renovation**

Responsible Employee	Progress Towards Completion	Recommended Phase
Brenda Rehnke Recreation Manager 623-773-7131	(insert periodic notes regarding steps taken or work completed)	PHASE ONE

1.7 Interior Accessible Route (includes common area and stairs) -
[\[CHECKLIST-INTERIOR\]](#) [\[CHECKLIST-RAMPS\]](#)

Interior Route: snack machine 54" reach [CC235](#), [CC236](#); lacks CFS at fire alarm pull with seating [CC234](#); AED protrudes 6" [CC232](#), [CC233](#); single bowl at water bottle fountain site [CC231](#); drinking fountain flow height exceeds 4" (checklist)

Ramps: center landing 48" x 51" [CC185](#), [CC186](#), [CC187](#), [CC188](#), [CC189](#)

Recommendations (Peoria Community Center is a site designated with accessible features so 1.7.1 through 1.7.6 is integral to compliance with title II program access test):

- 1.7.1 Upon replacement of vending machine; **acquire** model having operable parts at max 48" aff (CC235, CC236)
- 1.7.2 **Remove, or relocate storage** in CFS at fixtures and operable parts along the AR (CC234)
- 1.7.3 **Relocate protruding objects** along the interior AR or place cane detectable warning at foot of AED (CC232, CC233)
- 1.7.4 **Replace drinking fountain** with hi-lo bowl (CC231)
- 1.7.5 **Adjust** spout flow height to max 4" at drinking fountain (checklist)
- 1.7.6 **Enlarge landing** on ramp where directions change to 60" by 60" (CC185, CC186, CC187, CC188, CC189)

Responsible Employee	Progress Towards Completion	Recommended Phase
Brenda Rehnke Recreation Manager 623-773-7131	(insert periodic notes regarding steps taken or work completed)	PHASE ONE

1.8 Public Designated Use Spaces (includes classrooms, meeting rooms, special purpose rooms, and other spaces intended for use by the public) - [\[CHECKLIST\]](#)

Protruding Objects: fitness room- dance bars 6.75" [CC75](#), [CC76](#), television [CC77](#), [CC78](#); tot room- television 14" [CC84](#), [CC85](#); Calderwood room- sign 15" [CC105](#), [CC106](#); break room- television 12" [CC113](#), [CC114](#); saddleback room- television 14" [CC120](#), [CC121](#)

Clear floor space: fitness storage- storage at bikes [CC79](#); twin buttes- lacks at paper towels [CC93](#); meeting room- lacks at white board [CC118](#)

Reach Range: fitness room- 53” to stereo [CC73](#), [CC74](#); east/west wing room- paper towels and soap high over sink [CC83](#); tot room- paper towels and soap high over sink (checklist); twin buttes- paper towels and soaps high over sinks [CC94](#); Calderwood room- stereo controls 54” [CC107](#), [CC108](#), coffee controls 56” [CC109](#), [CC110](#); break room- microwave 63.5” [CC111](#), [CC112](#); saddleback room- soap and paper towels high over sink [CC124](#), [CC125](#)

Work Surfaces: office foyer- counter 39.75” [CC126](#), [CC127](#)

Sinks: east/west wing room- 36.5” [CC81](#), [CC82](#); tot room- 35.75” [CC86](#), [CC87](#); twin buttes- 36.25” [CC91](#), [CC92](#); break room- 36” [CC115](#), [CC116](#); saddleback room- 36” [CC122](#), [CC123](#)

Recommendations (Peoria Community Center is a site designated with accessible features so 1.8.1 through 1.8.5 is integral to compliance with title II program access test):

- 1.8.1 **Relocate protruding objects** in rooms indicated or place cane detectable warning at foot of dance bars, TV’s and room sign (CC75, CC76, CC77, CC78, CC84, CC85, CC105, CC106, CC113, CC114, CC120, CC121)
- 1.8.2 **Remove, or relocate storage** in CFS at fixtures and operable parts (CC79, CC93, CC118)
- 1.8.3 **Lower operating mechanisms** in rooms indicated to max 48” aff to highest operable part or 44” for a reach over a counter (CC73, CC74, CC83, CC94, CC107, CC108, CC109, CC110, CC111, CC112, CC124, CC125)
- 1.8.4 **Lower** counter height in office foyer to max 34” (CC126, CC127)
- 1.8.5 **Lower** sink heights to max 34” aff in rooms indicated (CC81, CC82, CC86, CC87, CC91, CC92, CC115, CC116, CC122, CC123)

Responsible Employee	Progress Towards Completion	Recommended Phase
Brenda Rehnke Recreation Manager 623-773-7131	(insert periodic notes regarding steps taken or work completed)	PHASE ONE

1.9 Employee Offices and Spaces - [\[CHECKLIST\]](#)

36” access aisle: storage near entry- lacks (checklist); east wing storage (table and chair)- storage to tables (checklist); twin buttes A storage- storage prevents [CC95](#), [CC96](#); Calderwood storage- storage [CC99](#); Calderwood table and chair storage- storage [CC103](#) ; Calderwood kitchen storage left- storage prevents [CC100](#)

60” turning space: game room storage- storage prevents [CC71](#); storage near entry- storage prevents [CC72](#); janitor storage near twin buttes A- lacks [CC88](#); twin buttes A storage- storage prevents (checklist); snack storage- shelves prevent (checklist); Calderwood storage- storage (checklist); Calderwood kitchen storage left- lacks (checklist); Calderwood janitor storage- not large enough, storage [CC101](#); stage storage C- storage [CC104](#); Paula’s office- desk [CC117](#)

Clear floor space: snack storage- fridge lacks due to shelves [CC97](#), [CC98](#)

Reach Range: janitor storage near twin buttes A- chemical mix 52" [CC89](#), [CC90](#);
 Calderwood janitor storage- chemical mix [CC102](#)

Recommendations (Peoria Community Center is a site designated with accessible features so 1.9.1 through 1.9.3 is integral to compliance with title II program access test):

- 1.9.1 Employee only area permit approach, entry, and exit, **relocate obstacles** such as tables and chairs to create AR through rooms indicated (CC95, CC96, CC99, CC103, CC100, checklist)
- 1.9.2 Employee only areas permit approach, entry, and exit, **relocate obstacles** to create turning space of 60" in rooms indicated (CC71, CC72, CC88, CC101, CC104, CC117, checklist)
- 1.9.3 For all other deficits, **leave as is**, employee work area pursuant to 2010 Standards 106.5 Defined Terms, until an employee with a disability works here (CC97, CC98, CC89, CC90, CC102)

Responsible Employee	Progress Towards Completion	Recommended Phase
Brenda Rehnke Recreation Manager 623-773-7131	(insert periodic notes regarding steps taken or work completed)	PHASE ONE

1.10 Assembly Areas - not applicable

1.11 Restrooms - [CHECKLIST-MULTIPLE USERS] Both: reach range- paper towel dispenser wave area [CC129](#), [CC130](#), [CC133](#), [CC154](#), hand sanitizer 49" [CC131](#), [CC132](#), [CC155](#), [CC156](#), sharps disposal 50" [CC133](#), [CC134](#), [CC152](#), baby changer 53" [CC163](#), [CC164](#); ambulatory stall sizes- men's 59.25" deep [CC135](#), women's 37.5" and 59.25" deep [CC150](#), [CC151](#), [CC158](#); ambulatory doors 22.5" wide [CC136](#), [CC158](#); coat hook in ambulatory stall 59.5" [CC137](#), [CC159](#), [CC160](#); toilet paper too close above grab bar- 6.5" men's [CC142](#), [CC143](#), 8" women's [CC161](#), [CC162](#); stall door location exceeds 4" [CC147](#), [CC148](#), [CC165](#), [CC166](#); toilet paper too close and adjacent to toilet [CC144](#), [CC162](#); shelves protrude 8" [CC145](#), [CC146](#)

Men's: grab bars 36.25" [CC139](#), [CC140](#), [CC141](#)

Recommendations (Peoria Community Center is a site designated with accessible features so 1.11.1 through 1.11.8 is integral to compliance with title II program access test): (Multiple Users)

- 1.11.1 **Lower** paper towel dispenser, hand sanitizer, sharps disposal and baby changer to max 48" to highest operable part in both (CC129, CC130, CC133, CC154, CC131, CC132, CC155, CC156, CC133, CC134, CC152, CC163, CC164)

- 1.11.2 **Reconfigure** ambulatory stalls in both to be 35" to 37" wide and min 60" deep (CC135, CC150, CC151, CC158)
- 1.11.3 **Replace stall door** of ambulatory stalls with one 32" wide, outward swinging and self-closing (CC136, CC158)
- 1.11.4 **Lower hooks** in accessible stalls to max 48" aff (CC137, CC159, CC160)
- 1.11.5 **Remount toilet paper dispensers** max 7" to 9" from front of toilet, 15" to 48" aff and min 12" above or 1.5" below grab bar in both (CC142, CC143, CC161, CC162, CC144)
- 1.11.6 **Rehang** stall door to be max 4" from adjacent stall partition and on the stall wall farthest from the toilet (CC147, CC148, CC165, CC166)
- 1.11.7 **Relocate or recess** shelves in both to not interfere with general circulation path, protrusions can't be greater than 4" (CC145, CC146)
- 1.11.8 **Remount** grab bars in men's accessible stall to 33" to 36" aff (CC139, CC140, CC141)

Responsible Employee	Progress Towards Completion	Recommended Phase
Brenda Rehnke Recreation Manager 623-773-7131	(insert periodic notes regarding steps taken or work completed)	PHASE ONE

[[CHECKLIST-SINGLE USER](#)] *Caterpillar*: toilet lacks side CFS due to urinal 28" from toilet [CC168](#), [CC169](#); toilet paper 7" above grab bar [CC170](#), [CC171](#); toilet paper too close and adjacent to toilet (checklist); paper towel wave control 54.5" [CC172](#), [CC173](#)

Hall Unisex: small trash can in toilet CFS [CC176](#); toilet paper 8" above grab bar [CC177](#), [CC178](#); toilet paper too close and adjacent to toilet (checklist); paper towels wave control 54" [CC181](#), [CC182](#), hand sanitizer 51" [CC179](#), [CC180](#), sharps disposal 49" [CC183](#), [CC184](#)

Recommendations (Peoria Community Center is a site designated with accessible features so 1.11.1 through 1.11.4 is integral to compliance with title II program access test): (Single Users)

- 1.11.1 **Leave as is**, lack of CFS adjacent to caterpillar toilet as CFS is present in front (CC168, CC169)
- 1.11.2 **Remount toilet paper dispensers** in both to max 7" to 9" from front of toilet, 15" to 48" aff and min 12" above or 1.5" below grab bar (CC170, CC171, CC177, CC178, checklist)
- 1.11.3 **Lower** paper towel dispensers in both and hand sanitizer and sharps disposal in hall RR to max 48" to highest operable part (CC172, CC173, CC181, CC182, CC179, CC180, CC183, CC184)
- 1.11.4 **Relocate** trash can in hall RR to be out of CFS of toilet (CC176)

Responsible Employee	Progress Towards Completion	Recommended Phase
Brenda Rehnke Recreation Manager 623-773-7131	(insert periodic notes regarding steps taken or work completed)	PHASE ONE

1.12 Kitchen/Concessions -

Calderwood (public): [[CHECKLIST-CALDERWOOD](#)] reduces to 21" wide at cutting board [CC190](#), [CC191](#); reduces to 20.5" by oven [CC192](#), [CC193](#); sink heights- dish sink 37.25" [CC194](#), [CC195](#), triple basin 37" [CC196](#), [CC197](#), double basin 36" [CC199](#), [CC200](#), rear hand sink 34.5" [CC201](#), [CC202](#); pipes lack insulation at all sinks (checklist); lacks knee clearance- double basin (checklist), hand wash near triple basin [CC198](#), dish sink (checklist), triple basin (checklist), rear hand sink due to pipes [CC203](#); protruding objects- cutting board counter 9" [CC204](#), [CC205](#), fire extinguisher 7" [CC206](#), [CC207](#); water collects on floor near dish sink [CC209](#), [CC210](#); slopes- 2.7% cross near freezer [CC213](#), [CC214](#), 11.3% running on ramp inside freezer [CC211](#), [CC212](#), 11% on ramp inside fridge [CC215](#), [CC216](#), 2.4% cross near fridge [CC217](#), [CC218](#); lacks CFS- rear hand sink due to movable counter [CC203](#), fire extinguisher due to storage [CC219](#); reach range- soap dispenser 49.5" over sink [CC220](#), paper towels 51" over sink [CC221](#), [CC222](#)

Recommendations (Peoria Community Center is a site designated with accessible features so 1.12.1 through 1.12.9 is integral to compliance with title II program access test): (Calderwood)

- 1.12.1 **Relocate** center prep table to provide 40" clear width for AR through kitchen (CC190, CC191, CC192, CC193)
- 1.12.2 **Lower** sink heights to max 34" aff to one of each type of sink (CC194, CC195, CC196, CC197, CC199, CC200, CC201, CC202)
- 1.12.3 **Insulate** exposed pipes on all lowered sinks (checklist)
- 1.12.4 **Remove** storage, or replace sink to provide knee and toe clearance at all lowered sinks (CC198, CC203, checklist)
- 1.12.5 **Relocate or recess** cutting board and fire extinguisher to not interfere with general circulation path, protrusions can't be greater than 4" (CC204, CC205, CC206, CC207)
- 1.12.6 **Repair drain** near dish sink to eliminate water accumulation (CC209, CC210)
- 1.12.7 **Correct or repair** slope of floor to max 5% running and 2.08% cross (CC213, CC214, CC211, CC212, CC215, CC216, CC217, CC218)
- 1.12.8 **Remove, or relocate storage** in CFS at fixtures and operable parts (CC203, CC219)
- 1.12.9 **Lower** soap and paper towels to max 46" for a forward reach over the sink (CC220, CC221, CC222)

Responsible Employee	Progress Towards Completion	Recommended Phase
Brenda Rehnke Recreation Manager 623-773-7131	(insert periodic notes regarding steps taken or work completed)	PHASE ONE

Caterpillar (public): [[CHECKLIST-CATERPILLAR](#)] sink 36.5" [CC223](#), [CC224](#); sink lacks knee clearance due to base cabinets [CC224](#); fire extinguisher protrudes 6.5" if cart moved [CC226](#), [CC227](#); reach range- paper towels 49" over counter [CC228](#), [CC229](#), soap high over counter (checklist)

Recommendations (Peoria Community Center is a site designated with accessible features so 1.12.1 through 1.12.3 is integral to compliance with title II program access test): (Caterpillar)

- 1.12.1 **Remove** base cabinet and **lower** sink height to max 34" aff (CC223, CC224)
- 1.12.2 **Relocate protruding objects** or place cane detectable warning at foot of fire extinguisher (CC226, CC227)
- 1.12.3 **Lower** soap and paper towels to max 46" for a forward reach over the sink (CC228, CC229, checklist)

Responsible Employee	Progress Towards Completion	Recommended Phase
Brenda Rehnke Recreation Manager 623-773-7131	(insert periodic notes regarding steps taken or work completed)	PHASE ONE

1.13 **Locker Rooms** - not applicable

1.14 **Aural and Visual Alarms** - [[CHECKLIST](#)] no issues

1.15 **Directional and Permanent Space Signs** - [[CHECKLIST](#)] exit signage overhead illuminated only [CC230](#)

Recommendations (Peoria Community Center is a site designated with accessible features so 1.15.1 through 1.15.3 is integral to compliance with title II program access test):

- 1.15.1 **Create template for signs** that addresses height of sign, size of characters, location of Braille, and other requirements (checklist)
- 1.15.2 **Implement a sign revision program** throughout the building, discriminating between directional signs and signs for permanent spaces (checklist)
- 1.15.3 **Mount signage** at all permanent rooms/spaces having Braille and the international symbol of accessibility, mounted at 60" to the middle of the sign and on the latch side of the door (CC230, checklist)

Responsible Employee	Progress Towards Completion	Recommended Phase
Brenda Rehnke Recreation Manager 623-773-7131	(insert periodic notes regarding steps taken or work completed)	PHASE ONE

1.16 Other - not applicable (see play area in next section)

PLAY AREA

- 1.1 **Parking** – see above
- 1.2 **Exterior Accessible Route** - see above
- 1.3 **Playground Designated Entry** - [[CHECKLIST](#)] lacks posted age group (checklist)

Recommendations (in the alternative, leave as is and designate playgrounds at other sites in the Department as accessible):

- 1.3.1 **Acquire and install** intended user signage and mount at designated entry as a smart practice (checklist)

Responsible Employee	Progress Towards Completion	Recommended Phase
Brenda Rehnke Recreation Manager 623-773-7131	(insert periodic notes regarding steps taken or work completed)	DEPARTMENT OPTION

- 1.4 **Playground Surface/Accessible Route within** - [[CHECKLIST](#)] no issues
- 1.5 **Transfer System** - [[CHECKLIST](#)] no issues
- 1.6 **Ramps** - not applicable
- 1.7 **Elevated Play Components** - [[CHECKLIST](#)] 5 of 7 EPCs compliant (checklist); apply incentive scoping due to lack of ramp
- 1.8 **Ground Level Play Components** - [[CHECKLIST](#)] does not meet incentive scoping due to lack of types (checklist)

Recommendations (in the alternative, leave as is and designate playgrounds at other sites in the Department as accessible):

- 1.8.1 **Add one more type** of GLPCs such as climbers, spinners or rockers, to meet incentive scoping (checklist)

Responsible Employee	Progress Towards Completion	Recommended Phase
Brenda Rehnke Recreation Manager 623-773-7131	(insert periodic notes regarding steps taken or work completed)	DEPARTMENT OPTION

- 1.9 **Sand box/Play tables** - not applicable
- 1.10 **Park Site** - not applicable
- 1.11 **Shelters/Picnic Areas** - not applicable

1.12 Park Buildings - not applicable

1.13 Other - not applicable

PEORIA COMMCTR SEC2