

REPORT TO THE CITY OF PEORIA COMMUNITY SERVICES DEPARTMENT

Section 5: Rio Vista Recreation Center

July 18, 2013

Legend of Abbreviations

aff... above the finished floor (or
above the finished ground)
AR... Accessible Route
CIL... Change in Level
CFS... Clear Floor Space
lbf... Pounds of Force

Background

RAC staff conducted an access audit at the Rio Vista Recreation Center. Our findings are below.

- 1.1 **Parking** - [[CHECKLIST](#)] need to determine where to draw line between rec cntr and park; one space lacks signage [RC1](#), all others lack violation (checklist); signs low [RC2](#), [RC3](#), [RC4](#), [RC5](#), [RC6](#), [RC7](#), [RC8](#), [RC9](#), [RC10](#), [RC11](#), [RC12](#), [RC13](#), [RC14](#), [RC15](#)

Recommendations (Rio Vista Recreation Center is a site designated as accessible so 1.1.1 and 1.1.2 is integral to compliance with title II program access test):

- 1.1.1 **Acquire and mount** at appropriate heights and locations accessible parking sign for stall (RC1)
 1.1.2 **Raise** existing accessible parking signs so lowest end of bottom sign is min 60" off (RC2, RC3, RC4, RC5, RC6, RC7, RC8, RC9, RC10, RC11, RC12, RC13, RC14, RC15)

Responsible Employee	Progress Towards Completion	Recommended Phase
Brenda Rehnke Recreation Manager 623-773-7131	(insert periodic notes regarding steps taken or work completed)	PHASE ONE

- 1.2 **Exterior Accessible Route (includes common area and stairs)-**
[\[CHECKLIST-EAR\]](#) [\[CHECKLIST-STAIRS\]](#) [\[CHECKLIST-RAMP\]](#)

Exterior Route: CIL at bollards [RC16](#)

Stairs:

Risers: lakeview east exit from patio- 5" to 5.5" [RC161](#), [RC160](#), [RC162](#); emergency exit from track- 6.5" to 7" [RC169](#), [RC168](#), [RC170](#), bottom riser not closed [RC167](#); lakeview west exit from patio- 5" to 5.5" [RC172](#), [RC171](#)

Treads: lakeview east exit from patio- 12.25" to 12.75" [RC163](#), [RC164](#), [RC165](#); lakeview west exit from patio- 12" to 13" [RC173](#), [RC174](#), [RC175](#)

Detectable Warning: all lack (checklist)

Ramp: 8.8% running slope on lower run [RC179](#), [RC180](#)

Recommendations (Rio Vista Recreation Center is a site designated as accessible so 1.2.1 through 1.2.5 is integral to compliance with title II program access test):

- 1.2.1 **Add fill** around bollards to eliminate CIL (RC16)

- 1.2.2 **Correct riser heights** on stairs so they are a consistent height between 4” to 7”; leave as is if technically infeasible (RC161, RC160, RC162, RC169, RC168, RC170, RC167, RC172, RC171)
- 1.2.3 **Correct tread depth** on stairs so they are 11” minimum and consistent, leave as is if technically infeasible (RC163, RC164, RC165, RC173, RC174, RC175)
- 1.2.4 **Install** detectable warning strip on top tread of each stairway as a smart practice (checklist)
- 1.2.5 **Correct slope** of ramp to max 8.33% (RC179, RC180)

Responsible Employee	Progress Towards Completion	Recommended Phase
Brenda Rehnke Recreation Manager 623-773-7131	(insert periodic notes regarding steps taken or work completed)	PHASE ONE

1.3 Exterior Entry Signage - [CHECKLIST] accessible entries lack access symbol (checklist)

Recommendations (Rio Vista Recreation Center is a site designated as accessible so 1.3.1 and 1.3.2 is integral to compliance with title II program access test):

- 1.3.1 **Mount signage** at inaccessible entrances directing patrons in wheelchairs to accessible entrance (checklist)
- 1.3.2 **Mount signage** at entrance designating it as accessible (checklist)

Responsible Employee	Progress Towards Completion	Recommended Phase
Brenda Rehnke Recreation Manager 623-773-7131	(insert periodic notes regarding steps taken or work completed)	PHASE ONE

1.4 Exterior Entry Doors - [CHECKLIST]

Maneuvering Clearance: kitchen to patio- sink 9” push side [RC46](#), [RC47](#); kitchen to service yard- liquor lockup [RC48](#); track exit- gaps due to grates [RC26](#)

LBF: 8 of 9 doors with closers exceed 8.5 lbf (checklist)

Closer: 2 of 9 doors are fast (checklist)

Other: exit near locker rooms lack egress (checklist); back hall to service yard- sidelight 54.5” [RC51](#), [RC52](#); track exit- leads to stairs (checklist)

Recommendations (Rio Vista Recreation Center is a site designated as accessible so 1.4.1 through 1.4.9 is integral to compliance with title II program access test):

- 1.4.1 For all doors along the public circulation route, **remove and rehang** door to open from the opposite side to create 12” of maneuvering clearance on the push side (RC46, RC47)
- 1.4.2 For all doors along the public circulation route, **relocate storage, furniture, and other obstacles** to create 60” maneuvering space around doors (RC48)
- 1.4.3 For all doors along the public circulation route, **provide** a firm and stable CFS at door with gaps a max of .5” and perpendicular to path of travel (RC26)
- 1.4.4 For all doors along the public circulation route, **inspect, adjust, and maintain** 8.5 lbf to open exterior doors as a smart practice (checklist)
- 1.4.5 For all doors along the public circulation route, **inspect, adjust, and maintain** closing speed on door closers so that doors do not close to 3” faster than 3 seconds when started at 70 degrees (checklist)
- 1.4.6 For all doors along the public circulation route, **extend a pathway** away from the building for emergency egress (checklist)
- 1.4.7 For all doors along the public circulation route, **replace doors** with ones having sidelight viewing windows max 43” aff (RC51, RC52)
- 1.4.8 No maneuvering clearance at door due to stairs, **leave as is**, correction is technically infeasible (checklist)
- 1.4.9 **Upon renovation**; make above corrections to employee only doors

Responsible Employee	Progress Towards Completion	Recommended Phase
Brenda Rehnke Recreation Manager 623-773-7131	(insert periodic notes regarding steps taken or work completed)	PHASE ONE

- 1.5 **Elevator or Lift** - [\[CHECKLIST\]](#) table blocks CFS [RC177](#); emergency controls 32” aff [RC178](#); reopening device not 20 sec (checklist)

Recommendations (Rio Vista Recreation Center is a site designated as accessible so 1.5.1 through 1.5.3 is integral to compliance with title II program access test):

- 1.5.1 **Relocate** table to be out of CFS of elevator controls (RC177)
- 1.5.2 **Raise** emergency controls to min 35” aff, leave as is if technically infeasible (RC178)
- 1.5.3 **Adjust re-entry timing** so door stays open for min 20 seconds (checklist)

Responsible Employee	Progress Towards Completion	Recommended Phase
Brenda Rehnke Recreation Manager 623-773-7131	(insert periodic notes regarding steps taken or work completed)	PHASE THREE

FIRST FLOOR

1.6 Interior Doors - [CHECKLIST]

Maneuvering Clearance: women's restroom- 13" pull side wall [RC17](#), [RC18](#); family restroom- 16" pull side wall [RC19](#), [RC20](#); gym storage near lockers storage [RC29](#), bleachers 16" pull side [RC27](#), [RC28](#); climbing access- too small [RC31](#); gym to admin-storage [RC34](#); admin storage near offices- storage [RC35](#); IT equipment- storage both sides [RC36](#), [RC60](#); Jackie's office- storage [RC37](#); kids' corner restroom- garbage [RC38](#); kid corner to game room- storage [RC40](#); East Brook- storage both sides [RC41](#), [RC42](#); West Brook- chair [RC44](#); Lakeview west small storage- storage [RC45](#); Lakeview east room to large storage double- file cabinet [RC58](#); Lakeview east storage to back hall- storage [RC49](#); fire riser hall entry- storage [RC54](#); Riverside storage- 42" back pull side [RC56](#), [RC57](#), lacks AR [RC55](#); Lakeview east to large storage- storage [RC58](#); men's lobby- 13" pull side [RC203](#)

Change in level: climbing access- 4" [RC32](#), [RC33](#)

LBF: 23 of 23 doors with closers exceed 5 lbf (checklist)

Closer: 9 of 23 doors are fast (checklist)

Recommendations (Rio Vista Recreation Center is a site designated as accessible so 1.6.1 through 1.6.7 is integral to compliance with title II program access test):

- 1.6.1 For all doors along the public circulation route, **remove and rehang** to swing outward rather than inward to provide 18" maneuvering clearance on the pull side of door (RC17, RC18, RC19, RC20, RC203)
- 1.6.2 For all doors along the public circulation route, **relocate storage, furniture, and other obstacles** to create 60" maneuvering space around doors (RC29, RC27, RC28, RC34, RC35, RC36, RC60, RC37, RC38, RC40, RC41, RC42, RC44, RC45, RC58, RC49, RC54, RC55, RC58)
- 1.6.3 **Leave as is**, climbing wall door; correction is technically infeasible (RC31, RC32, RC33)
- 1.6.4 For all doors along the public circulation route, **widen** AR to door to min 48" for maneuvering clearance (RC56, RC57)
- 1.6.5 For all doors along the public circulation route, **inspect, adjust, and maintain** 5 lbf to open interior doors (checklist)
- 1.6.6 For all doors along the public circulation route, **inspect, adjust, and maintain** closing speed on door closers so that doors do not close to 3" faster than 3 seconds when started at 70 degrees (checklist)
- 1.6.7 For employee only doors; make above corrections **upon renovation**

Responsible Employee	Progress Towards Completion	Recommended Phase
Brenda Rehnke Recreation Manager 623-773-7131	(insert periodic notes regarding steps taken or work completed)	PHASE ONE

1.7 Interior Accessible Route (includes common area and stairs) -

[\[CHECKLIST-INTERIOR\]](#) [\[CHECKLIST-STAIRS\]](#)

Interior Route: vending machine 57" aff [RC142](#), [RC143](#); garbage can in CFS of computer space [RC144](#); stairs 78.5" overhead [RC150](#), [RC151](#); protrusions- AEDs 7" [RC135](#), [RC136](#), phone 5" [RC141](#); drinking fountain knee clearance 26.25" [RC137](#), [RC139](#), [RC140](#); lacks compliant egress signage (checklist)

Service Counter: 41.5" upstairs deck [RC148](#), [RC149](#)

Stairs:

Risers: main- 6.5" to 7" [RC153](#), [RC154](#)

Treads: main- 14" to 14.5" [RC156](#), [RC157](#); nosing exceeds 1.5" over tread below [RC158](#), [RC159](#)

Recommendations (Rio Vista Recreation Center is a site designated as accessible so 1.7.1 through 1.7.10 is integral to compliance with title II program access test):

- 1.7.1 **Replace** vending machine with one having operable parts max 48" aff (RC142, RC143)
- 1.7.2 **Remove, or relocate storage** in CFS at fixtures and operable parts along the AR (RC144)
- 1.7.3 **Install** guard rail below stairway to warn of reduced overhead clearance (RC150, RC151)
- 1.7.4 **Relocate protruding objects** along the interior AR or place cane detectable warning at foot of AED and phone (RC135, RC136, RC141)
- 1.7.5 **Remount** drinking fountain to provide 27" knee clearance (RC137, RC139, RC140)
- 1.7.6 **Install** signage at egress doorways having tactile lettering and Braille (checklist)
- 1.7.7 **Lower** 36" wide segment of service counter to max 36" aff (RC148, RC149)
- 1.7.8 **Correct riser heights** on stairs to consistent height between 4" to 7", leave as is if technically infeasible (RC153, RC154)
- 1.7.9 **Correct tread depth** on stairs to 11" minimum and consistent, leave as is if technically infeasible (RC156, RC157)
- 1.7.10 **Reduce** nosing on tread to max 1.5" over tread below (RC158, RC159)

Responsible Employee	Progress Towards Completion	Recommended Phase
Brenda Rehnke Recreation Manager 623-773-7131	(insert periodic notes regarding steps taken or work completed)	PHASE ONE

1.8 Public Designated Use Spaces (includes classrooms, meeting rooms, special purpose rooms, and other spaces intended for use by the public) - [\[CHECKLIST\]](#)

Protruding Objects: kids center- first aid 5" [RC106](#), [RC107](#); Lakeview east- shelf 8" [RC123](#), [RC124](#); break area- first aid 5" [RC131](#), [RC132](#)

Floor Surfaces: kids center- loose rugs (checklist)

Clear Floor Space: adventure center- ping pong paddles [RC102](#), light switch [RC101](#); kids center- first aid [RC107](#); Riverside- AV panel [RC125](#)

Reach Range: racquetball court (2)- media player input 63" [RC97](#), [RC96](#); kids center- soap, paper towels over sink [RC105](#), first aid 65.5" [RC108](#), [RC109](#), light switch over counter [RC110](#); West Brook- paper towels, soap over sink [RC112](#); break area- paper towels, soap over counter [RC134](#)

Work Surfaces: adventure center- 25" wide [RC98](#), [RC100](#)

Sinks: kids center- 36.5" aff [RC103](#), [RC104](#); West Brook- 36.75" [RC111](#), [RC112](#); break area- 36.5" [RC133](#), [RC134](#)

Recommendations (Rio Vista Recreation Center is a site designated as accessible so 1.8.1 through 1.8.6 is integral to compliance with title II program access test):

- 1.8.1 **Relocate protruding objects** in kid's center, Lakeview East and break area or place cane detectable warning at foot of first aid kits and shelf (RC106, RC107, RC123, RC124, RC131, RC132)
- 1.8.2 **Secure** edges of rugs in kid's center to eliminate trip hazard (checklist)
- 1.8.3 **Remove, or relocate storage** in CFS at fixtures and operable parts (RC102, RC101, RC107, RC125)
- 1.8.4 **Lower operating mechanisms** in rooms indicated to max 48" aff to highest operable part or 46" for forward reach over sink/counter (RC97, RC96, RC105, RC108, RC109, RC110, RC112, RC134)
- 1.8.5 **Replace or add** a table in the adventure center, having 30" wide knee and toe clearances (RC98, RC100)
- 1.8.6 **Lower** sink height to max 34" aff in rooms indicated (RC103, RC104, RC111, RC112, RC133, RC134)

Responsible Employee	Progress Towards Completion	Recommended Phase
Brenda Rehnke Recreation Manager 623-773-7131	(insert periodic notes regarding steps taken or work completed)	PHASE ONE

1.9 Employee Offices and Spaces - [\[CHECKLIST\]](#)

36" access aisle: gym storage- storage [RC90](#); volleyball storage- storage [RC92](#), [RC93](#); IT equipment- equipment reduces to 35" [RC127](#), [RC128](#)

80" overhead: Lakeview storage hall- pipes 75.5" [RC116](#), [RC117](#)

60" turning space: IT equipment- equipment [RC128](#)

Protruding Objects: storage near rock wall- shelf 6" [RC88](#), [RC89](#); Lakeview storage hall- switches [RC114](#), [RC119](#); IT equipment- panel 15" [RC129](#), [RC130](#)

Clear floor space: storage near rock wall- MSDS, panel [RC89](#); volleyball storage- panel [RC92](#); front desk storage (2)- switches [RC95](#); Lakeview storage hall- switches [RC114](#), [RC119](#), [RC120](#); Lakeview east storage- MSDS [RC121](#), chemicals [RC122](#)

Reach Range: storage near rock wall- MSDS, panel [RC89](#); volleyball storage- panel [RC92](#); front desk- t-stat [RC94](#); Lakeview storage room- IT equipment [RC113](#); Lakeview storage hall- switches [RC114](#), [RC118](#), [RC119](#), fire panel [RC120](#); Lakeview east storage- MSDS [RC121](#), chemicals [RC122](#); IT equipment- equipment [RC128](#)

Recommendations (Rio Vista Recreation Center is a site designated as accessible so 1.9.1 through 1.9.3 is integral to compliance with title II program access test):

- 1.9.1 Employee only area permit approach, entry, and exit, **relocate obstacles** such as tables and chairs to create AR through storage rooms and IT (RC90, RC92, RC93, RC127, RC128)
- 1.9.2 Employee only areas permit approach, entry, and exit, **relocate obstacles** to create turning space of 60" in IT room (RC128)
- 1.9.3 For all other deficits, **leave as is**, employee work area pursuant to 2010 Standards 106.5 Defined Terms, until an employee with a disability works here (RC116, RC117, RC88, RC89, RC114, RC119, RC129, RC130, RC92, RC95, RC114, RC119, RC120, RC121, RC122, RC94, RC113, RC118, RC128)

Responsible Employee	Progress Towards Completion	Recommended Phase
Brenda Rehnke Recreation Manager 623-773-7131	(insert periodic notes regarding steps taken or work completed)	PHASE ONE

1.10 Assembly Areas – not applicable

1.11 Restrooms - [\[CHECKLIST-MULTIPLE USERS\]](#)

Lobby

Both: door too far from side partition- men's 5.5" [RC201](#), [RC202](#), women's 5" [RC181](#), [RC182](#)

Men's: lacks access symbol [RC198](#); toilet paper 7" above side grab bar [RC199](#), [RC200](#)

Women's: tampon dispenser protrudes 6.5" [RC183](#), [RC184](#)

Recommendations (Rio Vista Recreation Center is a site designated as accessible so 1.11.1 through 1.11.4 is integral to compliance with title II program access test): (Multiple Users-Lobby)

- 1.11.1 **Rehang** stall doors in both to be max 4" from adjacent stall partition and on the stall wall farthest from the toilet (RC201, RC202, RC181, RC182)
- 1.11.2 **Replace and mount** signage, including access symbol at men's (RC198)
- 1.11.3 **Remount toilet paper dispenser** max 7" to 9" from front of toilet, 15" to 48" aff and min 12" above or 1.5" below grab bar in men's (RC199, RC200)
- 1.11.4 **Relocate or recess** tampon dispenser to not interfere with general circulation path, protrusions can't be greater than 4" (RC183, RC184)

Responsible Employee	Progress Towards Completion	Recommended Phase
Brenda Rehnke Recreation Manager 623-773-7131	(insert periodic notes regarding steps taken or work completed)	PHASE ONE

Locker Room

Both: hair dryer 65" aff [RC211](#), [RC212](#), [RC188](#), [RC189](#); door too far from side partition- men's 7.5" [RC209](#), [RC210](#), women's 9" [RC190](#), [RC191](#)

Men's: lacks access symbol [RC205](#); toilet centerline 18.5" [RC206](#); toilet paper 7.5" above side grab bar [RC208](#)

Women's: mirror 40.25" aff [RC185](#), [RC187](#); sink 34.25" [RC186](#), [RC187](#); door not self-closing (checklist); tampon dispenser protrudes 6.5" [RC193](#), [RC194](#)

Recommendations (Rio Vista Recreation Center is a site designated as accessible so 1.11.1 through 1.11.8 is integral to compliance with title II program access test): (Multiple Users-Locker Rooms)

- 1.11.1 **Lower** hair dryers in both to max 48" to highest operable part (RC211, RC212, RC188, RC189)
- 1.11.2 **Rehang** stall doors in both to be max 4" from adjacent stall partition and on the stall wall farthest from the toilet (RC209, RC210, RC190, RC191)
- 1.11.3 **Replace and mount** signage, including access symbol at men's (RC205)
- 1.11.4 **Remount** toilets to 16" to 18" from the side wall to centerline in men's (RC206)
- 1.11.5 **Remount toilet paper dispenser** max 7" to 9" from front of toilet, 15" to 48" aff and min 12" above or 1.5" below grab bar in men's (RC208)
- 1.11.6 **Leave as is**, mirror and sink in women's, cite construction tolerance (RC185, RC187, RC186)
- 1.11.7 **Adjust** stall door to be self-closing in women's (checklist)
- 1.11.8 **Relocate or recess** tampon dispenser to not interfere with general circulation path, protrusions can't be greater than 4" (RC193, RC194)

Responsible Employee	Progress Towards Completion	Recommended Phase
Brenda Rehnke Recreation Manager 623-773-7131	(insert periodic notes regarding steps taken or work completed)	PHASE ONE

[[CHECKLIST-SINGLE USER](#)] *Family*: toilet paper 5" above side grab bar [RC204](#)

Kids: toilet seat 16" aff [RC217](#), [RC220](#); rear grab bar not centered correctly [RC219](#), [RC220](#); toilet paper 6" above side grab bar [RC221](#), [RC222](#)

Recommendations (Rio Vista Recreation Center is a site designated as accessible so 1.11.1 through 1.11.3 is integral to compliance with title II program access test): (Single Users)

- 1.11.1 **Remount toilet paper dispenser** max 7" to 9" from front of toilet, 15" to 48" aff and min 12" above or 1.5" below grab bar in both (RC204, RC221, RC222)
- 1.11.2 Seat height should be max 12" to 15" aff in a children's restroom, **replace toilet seat, or re-set or replace toilet** so that seat height is not more than 15" as a smart practice (RC217, RC220)
- 1.11.3 **Remount rear grab bar** to behind the toilet, 12" to one side of center and 24" to the other and 33" to 36" aff in kid's (RC219, RC220)

Responsible Employee	Progress Towards Completion	Recommended Phase
Brenda Rehnke Recreation Manager 623-773-7131	(insert periodic notes regarding steps taken or work completed)	PHASE ONE

- 1.12 Kitchen/Concessions -** [[CHECKLIST](#)] triple basin 35.5" aff [RC224](#), [RC225](#); hand wash 36" aff [RC233](#), [RC234](#); pipes lack insulation [RC225](#), [RC227](#), [RC232](#); triple basin and hand wash lack knee clearance [RC225](#), [RC234](#); reach range- paper towels 58.5" [RC228](#), [RC229](#), microwaves 64" [RC230](#), [RC231](#)

Recommendations (Rio Vista Recreation Center is a site designated as accessible so 1.12.1 is integral to compliance with title II program access test):

- 1.12.1 For all deficits, **leave as is**, employee work area pursuant to 2010 Standards 106.5 Defined Terms, until an employee with a disability works here (RC224, RC225, RC233, RC234, RC225, RC227, RC232, RC228, RC229, RC230, RC231)

Responsible Employee	Progress Towards Completion	Recommended Phase
Brenda Rehnke Recreation Manager 623-773-7131	(insert periodic notes regarding steps taken or work completed)	PHASE ONE

1.13 Locker Rooms - [\[CHECKLIST\]](#)

Both: lack designated lockers, men's 0 of 38 (checklist), women's 0 of 26 (2 with accessible bench) (checklist); noncompliant transfer shower dimensions- men's 37.25" deep (checklist), women's 37" wide by 39.75" deep [RC243](#), [RC244](#), [RC245](#), [RC246](#); controls high- men's handheld 70" [RC261](#), [RC262](#), women's diverter 50" [RC247](#), [RC249](#), handheld 67" [RC248](#), [RC249](#); controls not 15" max from seat centerline [RC263](#), [RC258](#); bench has 4" gap, 17" from rear wall [RC264](#), [RC265](#), [RC266](#), [RC267](#), [RC252](#), [RC253](#), [RC254](#)

Men's: bench 25" deep [RC256](#), [RC257](#)

Women's: hose too short (checklist); shower bench 21" at highest [RC250](#), [RC251](#)

Recommendations (Rio Vista Recreation Center is a site designated as accessible so 1.13.1 through 1.13.6 is integral to compliance with title II program access test):

- 1.13.1 **Designate 5% or no less than 1 locker** as accessible, mounting signage having the access symbol and hooks and operating mechanisms max 48" aff in both (checklist)
- 1.13.2 **Renovate shower stall**, if feasible, to compliant dimensions for a transfer shower of 36" deep by 36" wide with a 36" opening in both (RC243, RC244, RC245, RC246)
- 1.13.3 **Remount** shower controls to max 48" aff and 15" max from seat centerline towards shower opening in both (RC261, RC262, RC247, RC249, RC248, RC249, RC263, RC258)
- 1.13.4 **Remount** shower seat to the correct location and height in both showers (RC264, RC265, RC266, RC267, RC252, RC253, RC254, RC250, RC251)
- 1.13.5 **Reduce** bench in men's to max 24" deep (RC256, RC257)
- 1.13.6 **Replace** hose in women's with one min 59" long (checklist)

Responsible Employee	Progress Towards Completion	Recommended Phase
Brenda Rehnke Recreation Manager 623-773-7131	(insert periodic notes regarding steps taken or work completed)	PHASE ONE

1.14 Aural and Visual Alarms - [\[CHECKLIST\]](#) lacks alarms in racquetball courts (checklist)

Recommendations (Rio Vista Recreation Center is a site designated as accessible so 1.14.1 and 1.14.2 is integral to compliance with title II program access test):

- 1.14.1 **Install audible and visual alarms** in rooms and spaces where alarms have been installed since 1992 (checklist)

1.14.2 Upon renovation **install audible and visual** alarms in all rooms and spaces (checklist)

Responsible Employee	Progress Towards Completion	Recommended Phase
Brenda Rehnke Recreation Manager 623-773-7131	(insert periodic notes regarding steps taken or work completed)	PHASE ONE

1.15 **Directional and Permanent Space Signs** - [\[CHECKLIST\]](#) exit signs lack tactile and Braille (checklist)

Recommendations (Rio Vista Recreation Center is a site designated as accessible so 1.15.1 through 1.15.3 is integral to compliance with title II program access test):

1.15.1 **Create template for signs** that addresses height of sign, size of characters, location of Braille, and other requirements (checklist)

1.15.2 **Implement a sign revision program** throughout the building, discriminating between directional signs and signs for permanent spaces (checklist)

1.15.3 **Mount signage** at all permanent rooms/spaces having Braille and the international symbol of accessibility, mounted at 60" to the middle of the sign and on the latch side of the door (checklist)

Responsible Employee	Progress Towards Completion	Recommended Phase
Brenda Rehnke Recreation Manager 623-773-7131	(insert periodic notes regarding steps taken or work completed)	PHASE ONE

1.16 **Other** – not applicable

SECOND FLOOR

1.6 Interior Doors - [\[CHECKLIST\]](#)

Maneuvering Clearance: aerobics- storage [RC22](#); dance room- garbage [RC23](#); dance room storage (2)- storage [RC24](#); dance room storage from hall- storage (checklist)

LBF: 4 of 4 doors with closers exceed 5 lbf (checklist)

Closer: men's restroom is fast (checklist)

Recommendations (Rio Vista Recreation Center is a site designated as accessible so 1.6.1 through 1.6.4 is integral to compliance with title II program access test):

- 1.6.1 For all doors along the public circulation route, **relocate storage, furniture, and other obstacles** to create 60" maneuvering space around doors (RC22, RC23, RC24, checklist)
- 1.6.2 For all doors along the public circulation route, **inspect, adjust, and maintain 5 lbf** to open interior doors (checklist)
- 1.6.3 For all doors along the public circulation route, **inspect, adjust, and maintain** closing speed on door closers so that doors do not close to 3" faster than 3 seconds when started at 70 degrees (checklist)
- 1.6.4 For employee only doors; make above corrections **upon renovation**

Responsible Employee	Progress Towards Completion	Recommended Phase
Brenda Rehnke Recreation Manager 623-773-7131	(insert periodic notes regarding steps taken or work completed)	PHASE ONE

1.7 Interior Accessible Route (includes common area and stairs)

Interior Route: see first floor

Stairs: see first floor

1.8 Public Designated Use Spaces (includes classrooms, meeting rooms, special purpose rooms, and other spaces intended for use by the public) - [\[CHECKLIST\]](#)

36" access aisle: dance storage- floor storage [RC70](#)

60" turning space: aerobics storage (checklist)

Protruding Objects: dance room- drinking fountain [RC63](#), dance bars 7" [RC66](#), [RC67](#), TV 26" [RC68](#), [RC69](#); aerobics room- TV 26" [RC74](#), [RC75](#), drinking fountain [RC79](#); fitness- AED 7" [RC82](#), [RC83](#)

Clear floor space: dance room- fire extinguisher [RC64](#); dance storage- light switch [RC71](#); aerobics room- light switch [RC73](#); fitness- fire extinguisher [RC84](#), sweat wipes [RC85](#)

Reach Range: aerobics room- fan switch 72.5" [RC76](#), [RC77](#)

Recommendations (Rio Vista Recreation Center is a site designated as accessible so 1.8.1 through 1.8.5 is integral to compliance with title II program access test):

- 1.8.1 **Relocate obstacles** such as tables and chairs to create AR through dance storage (RC70)
- 1.8.2 **Relocate obstacles** such as tables and chairs to create turning space in aerobics storage (checklist)
- 1.8.3 **Relocate protruding objects** in dance room, aerobics room and fitness or place cane detectable warning at foot of items listed (RC63, RC66, RC67, RC68, RC69, RC74, RC75, RC79, RC82, RC83)
- 1.8.4 **Remove, or relocate storage** in CFS at fixtures and operable parts (RC64, RC71, RC73, RC84, RC85)
- 1.8.5 **Lower operating mechanisms** in aerobics room to max 48" aff to highest operable part (RC76, RC77)

Responsible Employee	Progress Towards Completion	Recommended Phase
Brenda Rehnke Recreation Manager 623-773-7131	(insert periodic notes regarding steps taken or work completed)	PHASE ONE

1.9 Employee Offices and Spaces - [\[CHECKLIST\]](#)

Clear floor space: fitness equipment storage- phone, MSDS [RC61](#), chemicals [RC62](#)

Reach Range: fitness equipment storage- phone, MSDS [RC61](#), chemicals [RC62](#)

Recommendations (Rio Vista Recreation Center is a site designated as accessible so 1.9.1 is integral to compliance with title II program access test):

- 1.9.1 For all deficits, **leave as is**, employee work area pursuant to 2010 Standards 106.5 Defined Terms, until an employee with a disability works here (RC61, RC62)

Responsible Employee	Progress Towards Completion	Recommended Phase
Brenda Rehnke Recreation Manager 623-773-7131	(insert periodic notes regarding steps taken or work completed)	PHASE ONE

1.10 Assembly Areas – not applicable

1.11 Restrooms - [[CHECKLIST-MULTIPLE USERS](#)]

Both: door too far from adjacent partition- men’s 7.5” [RC213](#), [RC214](#), women’s 5” (checklist)

Men’s: toilet paper 8” above side grab bar [RC215](#), [RC216](#); door not completely self-closing (checklist)

Women’s: sink 34.25” aff [RC195](#), [RC196](#); tampon dispenser protrudes 6.5” [RC197](#)

Recommendations (Rio Vista Recreation Center is a site designated as accessible so 1.11.1 through 1.11.5 is integral to compliance with title II program access test): (Multiple Users)

- 1.11.1 **Rehang** stall door to be max 4" from adjacent stall partition and on the stall wall farthest from the toilet (RC213, RC214, checklist)
- 1.11.2 **Remount toilet paper dispenser** max 7" to 9" from front of toilet, 15" to 48" aff and min 12" above or 1.5" below grab bar (RC215, RC216)
- 1.11.3 **Adjust stall door** in men’s to come to a complete close (checklist)
- 1.11.4 **Leave as is**, sink in women’s; cite construction tolerance (RC195, RC196)
- 1.11.5 **Relocate or recess** tampon dispenser to not interfere with general circulation path, protrusions can’t be greater than 4" (RC197)

Responsible Employee	Progress Towards Completion	Recommended Phase
Brenda Rehnke Recreation Manager 623-773-7131	(insert periodic notes regarding steps taken or work completed)	PHASE ONE

1.12 Kitchen/Concessions – not applicable

1.13 Locker Rooms – not applicable

1.14 Aural and Visual Alarms – see first floor

1.15 Directional and Permanent Space Signs – see first floor

1.16 Other – not applicable

PEORIA RIOVISTAREC SEC5